








MERKINTÖJEN SELITYS

-  nurmi A3
-  reunatuki (luonnonkivistä)
-  luiskattu reunatuki (luonnonkivistä)
-  päällysteen reuna
-  valaisinpylväs (nykyinen)

Linjan Alppitie pääpisteet

Nro	Paalu	X	Y	Sade
1	0	6678861416	25484894995	
2	4.096	6678862779	25484898858	70
3	19.984	6678866324	2548491431	
4	43.726	6678868978	25484937904	-100
5	62.858	6678872917	25484956595	
6	94.575	6678882391	25484986865	70
7	112.915	6678885527	25485004881	
8	153.35	6678887199	25485045282	



C	M	S	T/H
B	M	S	T/H
A	M	S	T/H
 <b>KAUNIAISTEN KAUPUNKI</b> YHDYSKUNTATOIMI KUNTATEKNIikka		<b>GRANKULLA STAD</b> SAMHÄLLSTEKNIK KOMMUNTEKNIK	
ALUE	KAAVA <b>Ak 108</b>	KAUP OSA 6	PIIRI SUUNN TARK 9.1.2020 Minna Raatikka HYV 9.1.2020 Jarkko Riipinen PPK TELA
NIMI	<b>ALPPITIE</b>		KLEHTI 18N, 180 HNR0 LITTYV
AIHE	KATU		KAAVA 1500 ETRS-GK25 KORKEUSJÄR NZ2000
PIIRI LAJI	ASEMAPIIRUSTUS		NRO <b>2273/002</b>
 HSY:n vesihuolto PL 100 00066 HSY p. (09) 15611		NRO	HYV TARK HYV TARK
GT	RONS		RONS <b>RAMBOLL</b> 20.12.2019
SUUNN			SUUNN Pekka Pylsy
TARK			TARK Madis Sisask